5-year Photo Comparisons for Belen2, 4 plots

VSWCD: Belen2

2011/2012 photos: taken January 12, 2012 by Joe Zebrowski, NMFWRI 2016/2017 photos: taken Dec 16, 2016 by Kathryn Mahan & Christopher Martinez, NMFWRI


Contact:

Kathryn Mahan, Ecological Monitoring Specialist, NMFWRI

Office: 505.426.217

Cell: 620.288.0333

Email: krmahan@nmhu.edu



New Mexico Forest and Watershed Restoration Institute П





B2_1C, facing center from as close to 66 feet as visually possible (2012 above, 2016 below)





B2_1N, facing north from center (2012 above, 2016 below)





B2_1E, facing east from plot center (2012 above, 2016 below)







B2_1S, facing south from center (2012 above, 2016 below)





B2_1W, facing west from center (2012 above, 2016 below)





B2_2C, facing center from as close to 66 feet as visually possible (2012 above, 2016 below)





B2_2N, facing north from plot center (2012 above, 2016 below)





B2_2E, facing east from center (2012 above, 2016 below)





B2_2S, facing south from plot center (2012 above, 2016 below)





B2_2W, facing west from center (2012 above, 2016 below)





B2_3C, facing center from as close to 66 feet as visually possible (2012 above, 2016 below)





B2_3N, facing north from center (2012 above, 2016 below)






B2_3E, facing east from center (2012 above, 2016 below)





B2_3S, facing south from center (2012 above, 2016 below)





B2_3W, facing west from center (2012 above, 2016 below)






B2_4C, facing center from as close to 66 feet as visually possible (2012 above, 2016 below)







B2_4N, facing north from center (2012 above, 2016 below)





B2_4E, facing east from center (2012 above, 2016 below)





B2_4S, facing south from center (2012 above, 2016 below)







B2_4W, facing west from center (2012 above, 2016 below)

